APPENDIX B: DOOR LOCATIONS (updated 02/11/26)

Bldg. #	Location	Manufacture	Activation (Sensor)	Door Type	Qty
161	South entrance	Stanley	Handicap/push plate	Dual Slide	2
219	West Exterior	Horton	Handicap/Push Plate	Dual Swing	1
300	West entrance	Stanley	Handicap/push plate	Single swing	1
417	S Interior to work area	Stanley	Push Plate	Dual Swing	1
417	S Interior to counter	Stanley	Push Plate	Dual Swing	1
417	Northwest Interior	Stanley	Push Plate	Dual Swing	1
417	North Interior	Stanley	Push Plate/Moton	Dual Swing	1
422	West Exterior	Horton	Presence	Double Slide	1
460	North side	Besam	Presence/ Moton	Double Slide	1
460	North side	Besam	Presence/Moton	Double Slide	1
460	North side	Besam	Presence/Moton	Double Slide	1
471	East entrance	Stanley	Handicap	Single swing	2
482	East entrance	Ditec	Motion	Single Swing	2
545	South Exterior	Besam	Presence	Bi-Part	1
660	East Exterior	Nabco Gyro	Presence/Moton	Double Slide	1
700	North Exterior	Besam	Presence/Moton	Double Slider	1
820	West entrance	Norton	Handicap	Single swing	2
908	Northeast	Stanley	Moton	Single Slider	1
913	Hanger entrance	Stanley	Handicap	Double swing	2
913	Flightline entrance	Stanley	Handicap	Single swing	2
913	hallway	Stanley	Handicap	Double swing	1
934	West Side	Stanley	Moton	Double Swing	1
945	North Main Entry	Horton	Presence/Interior Moton	Bi-Part	1
1022	Southwest Exterior	Stanley	Push Plate/Moton	Double Slide	1
1143	South Exterior	Nabco Gyro	Push Plate	Single Swing	1
1143	South Interior	Nabco Gyro	Push Plate	Single Swing	1
1143	Southwest Exterior	Nabco Gyro	Push Plate	Single Swing	1
1143	Southwest Interior	Nabco Gyro	Push Plate	Single Swing	1
1143	West Exit	Nabco Gyro	Push Plate	Single Swing	1
1150	East	Tormax	Push Plate/Moton	Double Swing	2
1150	West	Tormax	Push Plate/Moton	Double Swing	2
1540	Storefront/west side	Stanley	Presence/Interior Moton	Double Swing	6
1540	Bathrooms	Nabco Gyro	Handicap	Single Swing	4
9003	East exterior	Stanley	Presence/Interior Moton	Double slide	1
9003	hangar/hallway	Stanley	Handicap	Single Swing	2
				Total	**52**