SAN BERNARDINO NF SUPERVISORS' OFFICE

ELECTRICAL SWITCHGEAR AND POWER PICTURES

Southern California Edison Substation

SOUTHERN CALIFORNIA EDISON SUBSTATION

Tie in between SCE Transformer Secondary and Forest Service Switchgear where damage occurred

Tie in between SCE Transformer Secondary and Forest Service Switchgear where damage occurred

Internal view of busbars. Insulation melted and peeling off

Southern California Edison Secondary Feeder cables tie in to Forest Service Main Entrance Busbars

Switchgear Compartment

Switchgear Compartment

Switchgear Compartment

Switchgear Compartment

Switchgear Compartment

Possible Asbestos Insulation

Switchgear Compartment

Secondary Distribution Transformer and Generator Tie-in

SBNF Site Standby Generator