All changes are to PC 3 (Housing Assembly) on SH 3 of 6557926D

1. Zone F6: Delete (1.90) Reference dimension
2. Zone F6: Update 1.25 dimension to 0.756 +/- 0.030 and move the bottom measurement point for the dimension upward from the back of receptacle threads to the step in the receptacle body
3. Zone F3: Delete Datum C from True Position callout for the 0.0623/0.0625 holes
4. Zone E3: Delete True Position of 0.030 to Datums A/B/D for the receptacle threads
5. Zone B5: Replace 2x 1.90 dimension with 2x 1.406 +/- 0.030 and move top measurement point for the dimension downward from back of receptacle threads (Datum C) to the step in the receptacle body (located between current Datum C and the weld between the receptacle and the frame).
6. Zone B5: Delete 0.020 parallelism to Datum C
7. Zone A5: Delete True Position of 0.060 to Datum D/C/E and 0.005 to Datum D
8. Zone A4: Delete 1.125 basic dimension
9. Zone B4: Delete 1.625 basic dimension
10. Zone B3: Delete Datum C