CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Reference Plan



Exhibit A: Franklin Falls Dam Location Plan.

CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Informational Photo

Exhibit B: Existing wood burning stove and connection of stove pipe to galvanized pipe.

CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Informational Photo

Exhibit C: Existing wood burning stove approximate stovepipe diameter (Left) and approximate distance from masonry hearth wall to the far side ("back") of the existing stainless-steel tee for the flue liner system (Right).

CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Informational Photo

Exhibit D: Top of chimney showing the top plate mortared in place and top vent pipe at angle.

CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Informational Photo

Exhibit E: Masonry chimney on roof. Showing combustible material as lead flashing sealant/water barrier.

CHIMNEY REPAIRS
U.S. ARMY CORPS OF ENGINEERS
FRANKLIN FALLS DAM
FRANKLIN, NEW HAMPSHIRE
STATEMENT OF WORK

Informational Photo

Exhibit F: Masonry chimney for wood burning stove. Showing cleanout in basement.