US Department of Agriculture (USDA)

2026 ANF SUPERVISOR'S OFFICE EXTERIOR WOOD STAINING

Contents

Mechanical Yard 2nd Floor Arcadia Supervisors Office Building 4
South End of Arcadia Supervisors Office Building 5
West End of Arcadia Supervisors Office Building 6
North End of Arcadia Supervisors Office Building 7

Figure 1 Damaged Siding Near the HVAC Packaged Units..... 4
Figure 2 & Figure 3 Sections of Damaged Siding Near Mechanical Yard..... 4
Figure 4 Damaged Siding near Door Entry..... 5
Figure 5 & Figure 6 Damaged Siding Below Windows and Near Downspout..... 5
Figure 7 & Figure 8 Siding Damaged Above Stone Veneer..... 6
Figure 9 & Figure 10 Siding Damage Near Windows on West End..... 6
Figure 11 & Figure 12 Siding Damage Above Stone Veneer and Fascia Board Restore..... 7
Figure 13 Repair and Restore Wood Awning..... 7
Figure 14 & Figure 15 Siding Damaged and Fascia Board Restore..... 8
Figure 16 & Figure 17 Siding Damage..... 8

* The areas marked indicate the estimated locations of visible siding damage. It is the contractor's responsibility to determine the required repairs.

Mechanical Yard 2nd Floor Arcadia Supervisors Office Building

Figure 1 Damaged Siding Near the HVAC Packaged Units

Figure 2 & Figure 3 Sections of Damaged Siding Near Mechanical Yard

Figure 4 Damaged Siding near Door Entry

South End of Arcadia Supervisors Office Building

Figure 5 & Figure 6 Damaged Siding Below Windows and Near Downspout

Figure 7 & Figure 8 Siding Damaged Above Stone Veneer

West End of Arcadia Supervisors Office Building

Figure 9 & Figure 10 Siding Damage Near Windows on West End

North End of Arcadia Supervisors Office Building

Figure 11 & Figure 12 Siding Damage Above Stone Veneer and Fascia Board Restore

Figure 13 Repair and Restore Wood Awning



Figure 14 & Figure 15 Siding Damaged and Fascia Board Restore



Figure 16 & Figure 17 Siding Damage