Description of Work

The Bureau of Land Management, North Dakota Field Office requires the body damage resulting from a deer strike, to be repaired on a 2019 Ram 1500 ½ ton truck VIN# 1CRR7KG4KS666745 .

This statement of work (SOW) will include repairing or replacing all damaged body components to original manufacturer requirements.

Successful performance will result in all damaged body components, being repaired or replaced with factory matching paint.

Pictures of the damages are attached in this document.

The BLM will deliver and pick up the vehicle to the vendors location within 100 Miles of the Field Office.

GOODYEAR
WRANGLER