Scope of Work: CGC Waesche- Discrep 26068
PR- 52000PR260025788
Last update 06/04/26

Background:
The covers of the ASW Duplex Strainer no longer seats properly due to material corrosion and needs to be replaced. In addition to the cover being rusted out, there are internal leaks developing as well which can have a cascading problem.

Statement of Work:
Vendor to provide the following parts to CGC Waesche at Base Alameda. The provided parts must be shipped as a complete order and with standard commercial packaging to prevent damage to items while in transit.

Part number	Description	Quantity
P/N: ST053020BF11TS, NIIN: 011614867	Model 53 duplex strainer	2
P/N ST552SEXX BSKT NSN: 4720-01-433-2577	Basket strainer 12157966 Eaton FILT	4

Service:
RDD 03JUL26

Address:
CGC Waesche
1 Eagle Rd
Bldg 42
Alameda CA 94501
ATTN Catherine Kavanaugh

Technical Product Line POC
Christian Thorn
(510) 437-5483
Christian.P.Thorn@USCG.MIL