[redacted]

Customer: US GOVERNMENT

[redacted]

Insured:	US GOVERNMENT	Policy #:		Claim #:	
Type of Loss:		Date of Loss:		Days to Repair:	0
Point of Impact:					

[redacted]

VEHICLE

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

VIN:	3C7WR5HJ6GG324346	Interior Color:		Mileage In:	29,142	Vehicle Out:	
License:	3589S	Exterior Color:		Mileage Out:			
State:		Production Date:	6/2016	Condition:		Job #:	

TRANSMISSION	Dual Mirrors	Stereo	Head/Curtain Air Bags
Automatic Transmission	Privacy Glass	Search/Seek	**WHEELS**
4 Wheel Drive	**CONVENIENCE**	Auxiliary Audio Connection	Styled Steel Wheels
POWER	Air Conditioning	**SAFETY**	**PAINT**
Power Steering	Intermittent Wipers	Drivers Side Air Bag	Clear Coat Paint
Power Brakes	Tilt Wheel	Passenger Air Bag	**OTHER**
Power Windows	Cruise Control	Anti-Lock Brakes (4)	California Emissions
Power Locks	Message Center	4 Wheel Disc Brakes	**TRUCK**
Power Mirrors	**RADIO**	Traction Control	Rear Step Bumper
Heated Mirrors	AM Radio	Stability Control	Trailer Hitch
DECOR	FM Radio	Front Side Impact Air Bags	Trailering Package

[redacted]

Preliminary Estimate

Customer: US GOVERNMENT

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	#		VIN Label		1	[redacted]	0.2	
2	#		Tire label		1	[redacted]	0.1	
3	#		Mercury caution label		1	[redacted]	Incl.	
4	#		D&R Battery		1	[redacted]	0.2	
5	#		Setup and measure - Full Clamp		1		3.0 F	
6	#		Pre-pull Rocker and Floor		1		3.0 F	
7	**FRONT BUMPER**							
8		R&I	R&I bumper assy				1.5	
9		R&I	LT Filler molding painted				0.2	
10	**GRILLE**							
11		R&I	Grille black hexagon black surrnd				Incl.	
12	**FRONT LAMPS**							
13		R&I	LT R&I headlamp assy				0.4	
14		Repl	Aim headlamps		1		0.5	
15	**FENDER**							
16	*	Repl	LT Fender	68054339AJ	1	[redacted]	1.8	2.6
17			Add for Edging					0.5
18			Add for Clear Coat					0.1
19	**WINDSHIELD**							
20		R&I	Windshield Dodge w/o rain sensor			[redacted]	2.9	
21	#		Urethane		2			
22		R&I	RT Side molding				Incl.	
23		R&I	LT Side molding				Incl.	
24	**CAB**							
25	#		Structural diagnosis		1	[redacted]	1.0	
26	*	Sect	LT Uniside panel lock plr/cntr plr/rkr	68145097AD	1		19.0	5.6
27			Overlap Major Adj. Panel					-0.4
28	#		Feather, prime & block		1			3.0
29	#		Add for installation sleeves		1		3.0	
30		Sect	LT Inner uniside cntr plr & rocker	68066893AF	1		9.5	1.2
31			Overlap Major Adj. Panel					-0.4
32		Repl	LT Inner rocker	68672133AA	1		5.0	
33		Repl	LT Roof molding	55372461AB	1		0.4	
34		R&I	LT W'strip on body front door				0.5	
35		R&I	LT W'strip on body rear door				0.4	
36	*	Rpr	LT Lower support				4.0	
37	*	Rpr	Front floor pan				12.0	1.5
38		Repl	LT W/S pillar trim black, w/o leather	5LQ99TX7AD	1		Incl.	
39		Repl	Headliner all	5SX35BD1AE	1		2.3	
40		Repl	LT Sunvisor w/o illuminated	1VF23BD1AC	1		Incl.	

[redacted]

Preliminary Estimate

Customer: US GOVERNMENT

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

41		Repl	LT Upr ctr plr trim w/o leather gray	1MH97BD1AD	1	[redacted]	Incl.	
42		Repl	LT Rear pillar trim gray	1DX61BD1AB	1	[redacted]	Incl.	
43	**CONSOLE**					[redacted]		
44		R&I	R&I console assy			[redacted]	0.5	
45	**RESTRAINT SYSTEMS**					[redacted]		
46		Repl	LT Side impact sens	68284054AA	1	[redacted]	0.2	
47		Repl	LT Side air bag	68239855AB	1	[redacted]	0.4	
48		Repl	LT Head air bag crew cab	68161579AJ	1	[redacted]	0.8	
49		Repl	RT Outer belt assy 2500 gray	5KP961X9AI	1	[redacted]	0.7	
50		Repl	LT Outer belt assy 2500 gray	5KP991X9AH	1	[redacted]	0.7	
51	**SEATS & TRACKS**					[redacted]		
52	*	Repl	LT Seat back cover HD vinyl	5MV55LA8AA	1	[redacted]	1.0	
53	*	R&I	LT Seat cushion pad			[redacted]	0.5	
54		R&I	RT R&I front seat			[redacted]	0.4	
55		Repl	LT Seat adjuster	68050732AB	1	[redacted]		
56		R&I	LT R&I front seat			[redacted]	0.4	
57		R&I	R&I rear seat			[redacted]	0.6	
58	**FRONT DOOR**					[redacted]		
59	*	Repl	LKQ LT door assy +33%	68144729AF	1	[redacted]	5.2	3.8
60			Overlap Major Adj. Panel			[redacted]		-0.4
61	#		Disassemble LKQ door		1	[redacted]	2.0	
62	#		LKQ Cleanup		1	[redacted]	2.0	0.5
63	*	Repl	LT Lower seal crew & mega cab	55112358AE	1	[redacted]	Incl.	
64		Repl	LT Nameplate "RAM 2500"	68140250AC	1	[redacted]	0.2	
65	*	Repl	LT Door trim panel all black/gray	5NN272X9AB	1	[redacted]	Incl.	
66	#		Fit side panels		1	[redacted]	1.0	
67		Repl	LT Upper hinge	68058515AB	1	[redacted]	0.3	0.3
68		Repl	LT Lower hinge	68058519AC	1	[redacted]	0.3	0.3
69	**REAR DOOR**					[redacted]		
70	*	Repl	LKQ LT door assy; Crew & mega cab +33%	4589873AE	1	[redacted]	5.1	3.6
71			Overlap Major Adj. Panel			[redacted]		-0.4
72	#		Disassemble LKQ door		1	[redacted]	2.0	
73	#		LKQ Cleanup		1	[redacted]	2.0	0.5
74		R&I	LT R&I trim panel			[redacted]	0.5	
75		Repl	LT Upper hinge	68058523AA	1	[redacted]	0.3	0.3
76		Repl	LT Lower hinge	68058533AD	1	[redacted]	0.3	0.3
77			Clear Coat			[redacted]		2.5
78	**BACK GLASS**					[redacted]		
79	*	Repl	LKQ back glass; fixed glass +33%	DB11597YPY	1	[redacted]	2.0	
80	#		Urethane		2	[redacted]		
81	**PICK UP BOX**					[redacted]		
82		R&I	R&I box assy			[redacted]	2.5	
83	**VEHICLE DIAGNOSTICS**					[redacted]		

[redacted]

Preliminary Estimate

Customer: US GOVERNMENT

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

84	*	Rpr	Pre-repair scan		[redacted]	0.5	M	
85	*	Rpr	Post-repair scan		[redacted]	0.5	M	
86	#		Cover car	1	[redacted]	0.2	1	
87	#		Primer masking	1	[redacted]	0.2	1	
88	#		Corrosion protection	1	[redacted]	0.3		
89	#		Toner mix and color match	1	[redacted]			0.5
90	#		Westin Protrax 4 Step bars	1	[redacted]	1.0		
91	#		4-Wheel alignment	1	[redacted]			
92	#		Pickup and delivery from sublet vendor	1	[redacted]	1.0		
93					[redacted]			
94	#				[redacted]			

ESTIMATE TOTALS

Category	Basis	Rate	Cost $
Parts		[redacted]	
Body Labor	99.1 hrs		
Paint Labor	25.5 hrs		
Mechanical Labor	1.0 hrs		
Frame Labor	6.0 hrs		
Refinish Related	0.4 hrs		
Paint Supplies	26.9 hrs		
Other Charges			
Subtotal			
Grand Total			

[redacted]

Preliminary Estimate

[redacted]

Preliminary Estimate

Customer: US GOVERNMENT

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

PARTS SUPPLIER LIST

Line	Supplier	Description
59	Shaw Auto Parts - Team PRP P.O. BOX 4729 POCATELLO ID 83205 (208) 232-5952	#00052625 LKQ LT door assy +33% 000 BLACK Quote: CCC-264586163 Expires: 12/02/24
70	LKQ Corp 28520 Hwy 410 East Buckley WA 98321 (360) 829-1263	#~370633541 LKQ LT door assy; Crew & mega cab +33% Door Assembly, Rear LARAMIN,4DR,GJX9,PW L, (ELECTRIC REGULATOR), CREW ,S#ST0642 Quote: 2755486120 Expires: 01/09/25
79	LKQ Corp 28520 Hwy 410 East Buckley WA 98321 (360) 829-1263	#~381001349 LKQ back glass; fixed glass +33% Back Glass TRADSEMAN,4DR FIXED, NON-HEATED,S#$W1024 Quote: 2753500279 Expires: 01/06/25

[redacted]

[redacted]

[redacted]

***** PRELIMINARY ESTIMATE *****

[redacted]

Owner

[redacted]

Inspection

[redacted]

Repairer

[redacted]

Vehicle

2016 Dodge Ram 250/2500 Tradesman 4 DR Crew Cab Long Bed
8cyl 6.4 Liter Hemi
6-Speed Automatic

Lic Expire:		**VIN:**	3C7WR5HJ6GG324346
Prod Date:	06/2016	**Mileage:**	
Veh Insp# :		**Mileage Type:**	Actual
Condition:		**Code:**	N8532B
Ext. Color:	BRIGHT WHITE	**Int. Color:**	
Ext. Refinish:	Two-Stage	**Int. Refinish:**	
Ext. Paint Code:	PW7,W7	**Int. Trim Code:**	

[redacted]

2016 Dodge Ram 250/2500 Tradesman 4 DR Crew Cab Long Bed
Claim # :

Styled Steel Wheels	Theft Deterrent System	Tilt Steering Wheel
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trailer Hitch	USB Audio Input(s)	Vinyl Seats

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Bumper										
1	I	8		Bumper,Front	Repair				1.0*	SM
Front End Panel And Lamps										
2	N	973		Headlamps Aim	Additional Labor				0.4	SM
3	RI	56		Lens,Headlamp LT	R & I Assembly				INC	SM
4	RI	121		Mldg,Headlamp Housing LT	R & I Assembly				0.2	SM
5	RI	1032		Harness,Frt Lamp Wirin	R & I Assembly					ME
6	RI	1156		Bulb,Front Fog Lamp LT	R & I Assembly					SM
Front Body And Windshield										
7	EP	103		Fender,Front LT	Replace PXN				0.6	SM
8	L	103		Fender,Front LT	Refinish				2.8	RF
					1.9 Surface					
					0.5 Edge					
					0.4 Two-stage					
9	E	127		Nameplate,Fender LT	68149700AB				0.2	SM
10	NG	143		Windshield,Shaded	NAGS DW1993-GT				3.1	SM
				>> Must Remove to replace headliner						
Cab And Components										
11	E	50		Frame,Door Opening LT	68144985AA				40.5	SM
12	L	50	13	Frame,Door Opening LT	Refinish				7.5	RF
					4.5 Surface					
					1.5 Edge					
					0.6 Two-stage setup					
					0.9 Two-stage					
13	I	54		Reinf,Door Frame LT	Repair				6.0*	SM
14	L	54		Reinf,Door Frame LT	Refinish				2.8	RF
					2.8 Surface					
15	E	670		Airbag,Roof LT	68161579AJ				INC	ME
16	E	1386	02	Board,Running LT	68044495AD				INC	SM
17	E	883	01	Headliner,Roof	5SX35BD1AE				INC	SM
Dashboard And Components										
18	N	1987		Scan,Pre-Repair	Additional Labor					ME
19	N	1988		Scan,Post-Repair	Additional Labor					ME
Center Console And Seat Tracks										
20	E	863		Module,Airbag Control	68346749AB				0.2	ME
21	E	1816	01	Airbag,Front Seat LT	68359021AB				1.0	ME
22	E	516	01	Seatbelt,Front LT	5KS791DVAC				INC	SM
23	E	991	01	Buckle,Frt Seatbelt LT	5KU971K2AA				INC	SM
Front Doors										
24	E	207		Door Shell,Front LT	68144729AF				4.2	SM
25	L	207		Door Shell,Front LT	Refinish				3.8	RF
					2.3 Surface					
					1.0 Edge					
					0.5 Two-stage					
26	E	243		W/Strip,Frt Door Lwr LT	55112358AE				INC	SM

08/01/2024 04:26 PM

2016 Dodge Ram 250/2500 Tradesman 4 DR Crew Cab Long Bed
Claim # :

27	RI	281		W/Strip,Front Door LT	R & I Assembly	INC	SM
28	E	482		W/Strip,Front Door LT	68563581AB	INC	SM
29	RI	482		W/Strip,Front Door LT	R & I Assembly	INC	SM
30	E	277		W/Strip,Belt Outer LT	55112377AI	INC	SM
31	E	231	01	Pnl,Inner Door Trim LT	1VY491U7AG	INC	SM
32	E	119		N/Plate,Front Door LT	68140250AC	0.2	SM
33	RI	474		Mirror,Outer R/C LT	R & I Assembly	INC	SM
34	NG	215		Glass,Front Door T LT	NAGS DD11592-GT	INC	SM
35	RI	251		Channel,Front Glass Ru LT	R & I Assembly	INC	SM
36	EP	217		Module,Frt Dr Carrier LT	Replace PXN	0.5	SM
37	E	211		Hinge,Front Door Upr LT	68058515AA	INC	SM
38	L	211		Hinge,Front Door Upr LT	Refinish	0.3	RF
					0.3 Surface		
39	E	213		Hinge,Front Door Lwr LT	68058519AC	INC	SM
40	L	213		Hinge,Front Door Lwr LT	Refinish	0.3	RF
					0.3 Surface		
41	E	1098	02	Rod,Front Door Lock LT	68044857AA	INC	SM
42	EP	205		Lock,Front Door RT	Replace PXN	1.1	SM
43	EP	227		Handle,Front Door Otr LT	Replace PXN	0.1	SM
44	E	1230		Airbag Sensor,Frt Door LT	56038946AB	INC	ME
Rear Doors							
45	E	287		Door Shell,Rear LT	4589873AE	4.0	SM
46	L	287		Door Shell,Rear LT	Refinish	3.9	RF
					2.4 Surface		
					1.0 Edge		
					0.5 Two-stage		
47	RI	305		W/Strip,RR Door Lower LT	R & I Assembly	INC	SM
48	RI	331		W/Strip,Belt Outer LT	R & I Assembly	INC	SM
49	RI	303		W/Strip,RR Door Body LT	R & I Assembly	0.4	SM
50	RI	327		Pnl,Inner Door Trim LT	R & I Assembly	INC	SM
51	RI	530		Glass,Rear Door T LT	R & I Assembly	INC	SM
52	RI	528		Module,RR Dr Carrier L/R	R & I Assembly	INC	SM
53	RI	422		Handle,Rear Door Otr LT	R & I Assembly	INC	SM
Manual Entries							
54	EC			Cover Car Exterior	Replace Economy		SM
55	SB			Hazardous Waste Removal	Sublet Repair		SM
56	E			Mask For Prime	Replace OEM	0.5*	SM
57	E			Mask Jamb's And Openin	Replace OEM	0.5*	SM
57	Items						

MC	Message
01	CALL DEALER FOR EXACT PART # / PRICE
02	PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO.
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts
Other Parts
Paint & Materials 21.4 Hours
Parts & Material Total

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs
Sheet Metal (SM)		56.1	7.4	63.5
Mech/Elec (ME)		1.2		1.2
Frame (FR)				
Refinish (RF)		21.4		21.4

08/01/2024 04:26 PM

[redacted]

VEHICLE

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

VIN:	3C7WR5HJ6GG324346	Interior Color:	Mileage In:	Vehicle Out:
License:		Exterior Color:	Mileage Out:	
State:	MT	Production Date:	Condition:	Job #:

TRANSMISSION
Automatic Transmission
4 Wheel Drive

POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR
Dual Mirrors
Privacy Glass

CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Message Center

RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags

WHEELS
Styled Steel Wheels

PAINT
Clear Coat Paint

OTHER
California Emissions

TRUCK
Rear Step Bumper
Trailer Hitch
Trailering Package

[redacted]

[redacted]

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	**FENDER**							
2		Repl	LT Fender	68054339AJ	1	[redacted]	1.8	2.6
3			Add for Clear Coat					1.0
4			Add for Edging					0.5
5			Add for Clear Coat					0.1
6	**CAB**							
7		Repl	LT Uniside panel	68145097AD	1		19.0	5.6
8			Overlap Major Adj. Panel					-0.4
9			Add for Clear Coat					1.0
10		Repl	LT Inner rocker	68144997AC	1		5.0	
11		Repl	LT Inner uniside	68066893AF	1		11.5	3.0
12			Overlap Major Adj. Panel					-0.4
13			Add for Clear Coat					0.5
14	*	Rpr	Front floor pan				2.0	1.5
15	#	Subl	Hazardous waste removal		1			
16	*	Repl	LT Running board A/M	68190197AA	1		1.0	1.4
17			Overlap Major Non-Adj. Panel					-0.2
18	*		Add for Clear Coat					0.2
19	**RESTRAINT SYSTEMS**							
20		Repl	LT Head air bag regular cab	68184327AI	1		0.6	
21			Air bag system diagnosis				0.5	
22		Repl	Diagnostic unit 2500 crew & mega cab	68346749AB	1		0.4	
23		Repl	LT Side impact sens	68284054AA	1		0.2	
24		Repl	LT Outer belt assy 2500 beige	5KP991L1AH	1		0.7	
25		Repl	RT Outer belt assy 2500 beige	5KP961L1AI	1		0.7	
26	**FRONT DOOR**							
27		Repl	LT Door shell crew & mega cab	68144729AF	1		5.2	3.8
28			Overlap Major Adj. Panel					-0.4
29	*		Add for Clear Coat					0.7
30		Repl	LT Handle, outside w/o body color w/o keyless entry	55112383AE	1		Incl.	
31	**REAR DOOR**							
32		Repl	LT Outer panel	55372021AB	1		6.2	2.6
33			Overlap Major Adj. Panel					-0.4
34	*		Add for Clear Coat					0.4
35			Add for power units				0.4	
36			Add for Edging					0.5
37			Add for Clear Coat					0.1
38			Add for Inside					0.5
39			Add for Clear Coat					0.1
40	#	Subl	Hazardous waste removal		1			
41	#	Repl	Cover Car		1			

[redacted]

Preliminary Estimate

Customer: Forest Service 6049

Job Number:

2016 RAM 2500 Tradesman Crew Cab 169" WB 4WD 4D LONG 8-6.4L Gasoline Sequential MPI

42	**VEHICLE DIAGNOSTICS**					
43	*	Subl	Pre-repair scan	1	[redacted]	X m
44		Repl	Pre-repair scan	1	[redacted]	m
45	*	Subl	Post-repair scan	1	[redacted]	X m
46	*	Subl	Program module	1	[redacted]	X m
			SUBTOTALS		[redacted]	

ESTIMATE TOTALS

Category	Basis		[redacted]
Parts			
Body Labor	55.2 hrs	@	
Paint Labor	24.3 hrs	@	
Paint Supplies	24.3 hrs	@	
Miscellaneous			
Subtotal			
Grand Total			
Deductible			
CUSTOMER PAY			
INSURANCE PAY			

[redacted]

Attachment 3 Quotes of Suggested Repairs