Alarms 0
Supers 0
Securities 0
Troubles 1
SD WOMENS RESTROOM 107
May 19
Device
Input source malfunction
IN
MENU
Acknowledge Troubles
Reset System
101

Alarms 0
Supers 0
Troubles 1
B160 PS BY CARPENTER SHOP
1
May 17
Device
Multiple response
IN
160
Acknowledge Troubles
Reset System


Alarms 0
Supers 0
Securities 0
Troubles 3
PSC-12 MAIN FACP
1 May 21 Module Positive ground fault IN
MLC LOOP 8
1 May 21 Module Positive ground fault IN
MLC LOOP 7
1 May 21 Module Positive ground fault IN


Alarms 0
Supers 0
Securities 0
Troubles 21
Custom Message Not Programmed
1 12:44 Device Unspecified Device Respondi IN
Custom Message Not Programmed
1 12:44 Device Unspecified Device Respondi IN
Custom Message Not Programmed
1 12:44 Device Incorrect ID IN
Custom Message Not Programmed
1 12:44 Device Unspecified Device Respondi IN
Custom Message Not Programmed
1 12:44 Device Incorrect ID IN
Acknowledge Troubles
Reset System

S. BUILDING PIV
1
Apr 23
Tamper
IN
Acknowledge Supervisories
Reset System
Lower Galley


Alarms 0
Supers 0
Securities 0
Troubles 3
SSD MAIN LOBBY ENTRANCE
1
12:29
Module
Configuration Process Failur
IN
SSD MAIN LOBBY ENTRANCE
1
12:29
Module
Not responding
IN
1ST FL.PAD-3 ELEC RM# 106
1
12:29
Device
Trouble causing input
IN

ALARMS
000
SUPERS
000
SECURITIES
000
TROUBLES
025
1ST FL. SOUTHWEST EXIT
1 Dec 17 Manual Not Responding IN
1ST FL. SOUTHEAST EXIT
1 Dec 17 Manual Not Responding IN
1ST FL.SOUTH LOBBY
1 Dec 17 Smoke Not Responding IN
1ST FL.SO.MAINT.LOCKER
1 Dec 17 Smoke Not Responding IN
1ST FL.NO.LOBBY ENTRY
1 Dec 17 Manual Not Responding IN
Acknowledge Troubles
Reset System

ALARM
SUPERVISORY
SECURITY
TROUBLE
POWER
AUDIBLES
ON
SILENCED
PARTIAL SYSTEM DISABLED
CPU FAIL
Troubles 46
4TH FL.SOUTHWEST STAIRS
4TH FL.CORRIDOR BY RM#461
4TH FL.NO.CORRIDOR STAIRS
2ND FL SOUTHEAST STAIRS
2ND FL IN RM 212
MENU
ESC