Government Response to RFCs

11) Question: SOW States: Develop and submit to the GDO for review and approval a blocking plan to set and align the docking blocks in accordance with the requirements of drawing 200-997-001 for guidance. We are unable to locate Referenced Drawing 200-997-001 in the drawing index. Can this be provided?
Answer: Drawing 200-997-001 has removed. Replaced with correct DWG 124A-305-02. Please see updated Statement of Work – Errata 2.

---

12) Question: SOW States: Remove existing and install new remote fuel shut off switch for fuel tank quantity (2 EA) IAW LAW 60-DS-2101, and use drawing 124A-502 for guidance. LAR 60-DS-2101 was not included in the LAR package. Can this be provided?
Answer: LAR 60DS-2101 is now available.