Corporate Office
P.O. Box 541
Lawrence, PA 15055
(724) 745-1854
(724) 745-2184 (fax)

Columbus Office
865 Eastwind Drive
Westerville, OH 43081
(614) 392-2222
(614) 392-2300 (fax)

Customer Information		System Information		Job Information	
Facility	VA Medical Center Erie	**System Description**	Rietschle Duplex Medical Vacuum	**Job #**	622374
Address	135 East 38th Street	**System Model #**	CHBD-341-243 SYSTEM	**SO #**	622374
	Erie,PA 16504	**System Serial #**	3000496097	**Trip #**	1
Contact	David Dombkowski	**Manufacture Date**	None	**Year**	2024
Email	david.dombkowski@va.org	**System Location**	Penthouse 8th floor (7th fl up sta	**Date**	12/11/24
Phone	814-860-2924	**Customer System #**	None	**Tech**	RG/TP

Pump #	#1		#2		#3		#4	
Model #	H/EH341(12)100923-1		H/EH341(12)100923-1					
Serial #	1742146 (96)		1735925 (96)					
Run Hours	76,698		76,811					
Room Temperature	74°F							
Discharge Temperature	137°F		141°F					
Exhaust Drip Leg	A		A					
Exhaust Filters	A		A					
Ballast Filters	A		A					
Inlet Filters	A		A					
Oil and Oil Filters	R	12/11/24	R	12/11/24				
High Temp Shutdown								
Coupling	A		A					
Motor Greased	A		A					
Starter Contacts	A		A					
Thermal Overload Settings	48.00 AMPS		48.00 AMPS					
Transformer Condition	A							
Panel Lamps	A							
Panel Relays	A							
Lead Vac Switch	18-23	inHG						
Lag 1 Vac Switch	16-21	inHG						
Lag 2 Vac Switch		inHG						
Lag 3 Vac Switch		inHG						

Local Lag Alarm	
Audible	Yes
Visual	Yes

LEGEND
A = Acceptable
U = Unacceptable
R = Repaired
NR = Needs Replaced
NA = Not Applicable

Motor Information Section		Motor #1	Motor # 2	Motor # 3	Motor #4
Volts L1 to L2	205	32.90 AMPS	31.90 AMPS		
Volts L2 to L3	203	32.90 AMPS	32.10 AMPS		
Volts L1 to L3	204	32.70 AMPS	32.90 AMPS		

Efficiency	90.20%	**Service Factor**	1.15	**Horse Power**	15	**RPM**	1,165
Frame Size	284TC	**Voltage**	230	**Full Load Amps**	40		

Corporate Office
P.O. Box 541
Lawrence, PA 15055
(724) 745-1854
(724) 745-2184 (fax)

Columbus Office
865 Eastwind Drive
Westerville, OH 43081
(614) 392-2222
(614) 392-2300 (fax)

Parts Used		
Quantity	**Part Number**	**Part Description**
5	R590	OEM SYNTHETIC OIL CUSTOMER STOCK

Deficiencies
None

Comments
Change oil both pumps, clean and blow out coolers, flush oil out of coolers and exhaust box sumps 1,2.
Foam Clean Coolers
Pumps have high hours-oil levels and clarity okay well maintained

Recommendations
Maintain PM Frequency