STATEMENT OF WORK (SOW)
FOR
WMSL-753 Cross Connect Gear Heat Exchanger Parts Procure

1. **OBJECTIVE**
   1.1. CGC HAMILTON requires Alfa Laval parts for a heat exchanger repair. This Statement of Work (SOW) outlines the need for the requested parts outlined by manufacturer's drawings and specifications.
2. **REFERENCES**
   2.1. N/A
3. **TASKS**
   3.1. Conduct procurement of the Alfa Laval parts listed in the table below:

Item Description	Part Number/NSN Number	Quantity Requested
CHANNEL PLATE M10B2-TI-0.4-NBRP/C-4H	3675412403	211
END PLATE FIELD GASKET M10B-NBRP-C/RIB	390084017306	1
RUBBER LINING M10 NBRP T=31 STUD BOLT SIDE Ø144, PLATE PACK SIDE Ø156 MAX.	3450485102	4
PRESSED COLLAR M10 TI OD=156 ID=88 for Rubber lining,for D100,DN100	32324672411	4
DISTANCE RING M10 143x163x5 EN ISO 2081-Fe/Zn20A	3232473272	4

   3.2. The requested delivery date is no later than 01-AUG-2026.
   3.3. The provided parts must be shipped as a complete order and with standard commercial packaging to prevent damage to items while in transit. When order is shipped, the company must provide the USCG point of contact with shipment tracking information to the given shipping address.
   3.4. The parts shall be shipped to the following address:
   USCG HAMILTON DISCREP
   ATTN: LTJG CLAIRE PORTIGUE
   1050 REGISTER ST.
   NORTH CHARLESTON, SC 29405
4. **POINTS OF CONTACT**
   4.1. Please contact LTJG Bryan Chan at (510) 882-0364 or bryan.e.chan@uscg.mil with questions regarding this SOW.
5. **NOTES**
   5.1. N/A