

This pillow ticking is not acceptable. The opening should be folded inside and the sewing should be on the inside not outer edge.