TECHNICAL EXHIBIT 2 - PICTURES

CLIN 0002 NE Stairwell and Hangar Entry – Remove panels and equipment

CLIN 0002 NE Stairwell and Hangar Entry – Remove panels and equipment Panel D used as a pass-thru to Panel HH. Remove and refeed Panel HH.

CLIN 0003 Center Wind Tunnel – Correct noted deficiencies.

CLIN 0004 SE Stairwell and Hangar Entry – Remove panels & fuses and refeed Panel II (2nd Floor)

CLIN 0004 SE Stairwell and Hangar Entry – S5 & CB1

Remove S-5 and replace CB1 in location of S-5 with new panel. Refeed Panel II (2nd Floor and existing panel CB1 circuits)

CLIN 0005 SW Stairwell – Remove Panels & fuses and refeed Panel JJ (2nd floor)



CLIN 0006 (Optional) NE Stairwell and Hangar Entry – Panel FF – Install new Manual Transfer SW for Generator