Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01474

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC-1-1A; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01474-001	1-DM		White Adhesive; Homogeneous	5% Chrysotile	95% Non-Fibrous
			Total Asbestos:	5%	
13-08-01474-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01474-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01474-004	4-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous
13-08-01474-005	5-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous
13-08-01474-006	6-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01474

Project/Test Address: Audie Murphy VA - 1st Interstitial
AC-1-1A; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01474-007	7-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous
13-08-01474-008	8-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous
13-08-01474-009	9-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous

QC Sample: 18-M11995-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Araceli Enzler

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9 PLM

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

A

13-08-01474

Due Date:
08/15/2013
(Thursday)
AE

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-1A **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

_____ 1 - Day _____ 2 - Day ✓ 3 - Day _____ Same Day (Must Call Ahead) _____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop	Signature: [signature]	Date/Time: 8/9/13
Received by: KTHARRIS	Signature: K Harris	Date/Time:

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01463

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC 1-1D; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01463-001	1-FM		White Brittle; Homogeneous	NAD	1% Cellulose 99% Non-Fibrous
13-08-01463-002	2-FM		White Brittle; Homogeneous	NAD	1% Cellulose 99% Non-Fibrous
13-08-01463-003	3-FM		White Brittle; Homogeneous	NAD	1% Cellulose 1% Fibrous Glass 98% Non-Fibrous
13-08-01463-004	4-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01463-005	5-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01463

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-1D; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01463-006	6-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01463-007	7-PM		Off-White Pliable; Homogeneous	NAD	3% Fibrous Glass 7% Wollastonite 90% Non-Fibrous
13-08-01463-008	8-PM		Off-White Pliable; Homogeneous	NAD	1% Cellulose 2% Fibrous Glass 7% Wollastonite 90% Non-Fibrous
13-08-01463-009	9-PM		Off-White Pliable; Homogeneous	NAD	1% Cellulose 2% Fibrous Glass 7% Wollastonite 90% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01463

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-1D; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 13-M11996-1

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Mark Case

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9 PLM

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01463

Due Date:
08/15/2013
(Thursday)
AE

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-1D **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM - NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-FM	8/8/13	✓												Float Mud
2	2-FM	8/8/13	✓												"
3	3-FM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop	Signature:	Date/Time: 8/9/13
Received by: KT HARRIS	Signature: K Harris	Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01476

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-1E; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01476-001	1-DM		White Pliable; Brown Fibrous; Silver Foil-Like; Inhomogeneous	3% Chrysotile	10% Cellulose 87% Non-Fibrous
			Total Asbestos:	3%	
Chrysotile present in white pliable material.					
13-08-01476-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01476-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01476-004	4-CM		White Granular; Brown Fibrous; Inhomogeneous	NAD	50% Cellulose 50% Non-Fibrous
13-08-01476-005	5-CM		White Granular; Brown Fibrous; Inhomogeneous	NAD	50% Cellulose 50% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01476

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-1E;
San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01476-006	6-CM		White Granular; Brown Fibrous; Inhomogeneous	NAD	50% Cellulose 50% Non-Fibrous
13-08-01476-007	7-PM		White Pliable; Yellow Fibrous; Inhomogeneous	NAD	2% Cellulose 18% Fibrous Glass 5% Wollastonite 75% Non-Fibrous
13-08-01476-008	8-PM		White Pliable; Black Foam-Like; Inhomogeneous	2% Chrysotile	2% Cellulose 96% Non-Fibrous
			Total Asbestos:	2%	

Chrysotile present in white pliable material.

13-08-01476-009	9-PM			Did Not Analyze (Positive Stop)	

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01476

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-1E;
San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 18-M11995-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Timothy Harris

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9PLM

EHS Laboratories™

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01476

Due Date:
08/15/2013
(Thursday)
AE

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-1E **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop	Signature: [signature]	Date/Time: 8/9/13
Received by: KT HARRIS	Signature: K Harris	Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01470

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC 1-2A; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01470-001	1-DM		Off-White Pliable; Homogeneous	3% Chrysotile	1% Fibrous Glass 1% Talc 95% Non-Fibrous
			Total Asbestos:	3%	
13-08-01470-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01470-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01470-004	4-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01470-005	5-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01470

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-2A; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01470-006	6-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01470-007	7-PM		White to Pale Beige Pliable; Homogeneous	NAD	8% Wollastonite 92% Non-Fibrous
13-08-01470-008	8-PM		White to Pale Beige Pliable; Homogeneous	NAD	8% Wollastonite 92% Non-Fibrous
13-08-01470-009	9-PM		White to Pale Beige Pliable; Homogeneous	NAD	8% Wollastonite 92% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01470

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-2A; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 13-M11996-1

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Mark Case

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9PLM

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

13-08-01470

Due Date:
08/15/2013
(Thursday)
AE

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-2A **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop Signature: [illegible] Date/Time: 8/9/13

Received by: KT HARRIS Signature: K Harris Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01458

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/14/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC 1-2B; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01458-001	1-DM		White Brittle; Clear Adhesive; Inhomogeneous	NAD	100% Non-Fibrous
13-08-01458-002	2-DM		White Brittle; Clear Adhesive; Inhomogeneous	NAD	100% Non-Fibrous
13-08-01458-003	3-DM		White Brittle; Clear Adhesive; Inhomogeneous	NAD	100% Non-Fibrous
13-08-01458-004	4-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous
13-08-01458-005	5-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01458

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-2B; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01458-006	6-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous
13-08-01458-007	7-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous
13-08-01458-008	8-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous
13-08-01458-009	9-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01458

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-2B; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 18-M11995-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Sami Hosn

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9PLM

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01458

Due Date:
08/15/2013
(Thursday)
AE

S

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-2B **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop Signature: [signature] Date/Time: 8/9/13

Received by: KT HARRIS Signature: [signature] Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01464

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC 1-3E; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01464-001	1-DM		Off-White Pliable; Homogeneous	3% Chrysotile	1% Fibrous Glass 1% Talc 95% Non-Fibrous
			Total Asbestos:	3%	
13-08-01464-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01464-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01464-004	4-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01464-005	5-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01464

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-3E; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01464-006	6-CM		Tan Fibrous; White Brittle; Inhomogeneous	NAD	70% Cellulose 30% Non-Fibrous
13-08-01464-007	7-PM		Off-White Pliable; Inhomogeneous	NAD	8% Wollastonite 92% Non-Fibrous
13-08-01464-008	8-PM		Off-White Pliable; Inhomogeneous	NAD	8% Wollastonite 92% Non-Fibrous
13-08-01464-009	9-PM		Off-White Pliable; Inhomogeneous	NAD	8% Wollastonite 92% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01464

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-3E; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 13-M11996-1

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Mark Case

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

4PLM

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01464

Due Date:
08/15/2013
(Thursday)
AE

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-3E **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop	Signature: [signature]	Date/Time: 8/9/13
Received by: KT HARRIS	Signature: K Harris	Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01471

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC 1-4A; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01471-001	1-DM		White Adhesive; Homogeneous	5% Chrysotile	95% Non-Fibrous
			Total Asbestos:	5%	
13-08-01471-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01471-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01471-004	4-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous
13-08-01471-005	5-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous
13-08-01471-006	6-CM		Brown Wood; White Brittle; Inhomogeneous	NAD	15% Cellulose 85% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01471

Project/Test Address: Audie Murphy VA - 1st Interstitial AC
1-4A; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01471-007	7-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous
13-08-01471-008	8-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous
13-08-01471-009	9-PM		White Adhesive; Homogeneous	NAD	5% Wollastonite 95% Non-Fibrous

QC Sample: 18-M11995-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Araceli Enzler

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9 PLM

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01471 A

Due Date:
08/15/2013
(Thursday)
AE

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-4A **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop Signature: [signature] Date/Time: 8/9/13

Received by: KT HARRIS Signature: [signature] Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01478

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/13/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC-1-4E; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01478-001	1-DM		Off White Adhesive; Homogeneous	2% Chrysotile	1% Wollastonite 97% Non-Fibrous
			Total Asbestos:	2%	
13-08-01478-002	2-DM			Did Not Analyze (Positive Stop)	
13-08-01478-003	3-DM			Did Not Analyze (Positive Stop)	
13-08-01478-004	4-CM		White Brittle; Tan Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous
13-08-01478-005	5-CM		White Brittle; Tan Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous
13-08-01478-006	6-CM		White Brittle; Tan Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01478

Project/Test Address: Audie Murphy VA - 1st Interstitial
AC-1-4E; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01478-007	7-PM		Off White Adhesive; Homogeneous	NAD	1% Cellulose 6% Wollastonite 93% Non-Fibrous
13-08-01478-008	8-PM		Off White Adhesive; Homogeneous	NAD	1% Cellulose 6% Wollastonite 93% Non-Fibrous
13-08-01478-009	9-PM		Off White Adhesive; Homogeneous	NAD	6% Wollastonite 94% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01478

Project/Test Address: Audie Murphy VA - 1st Interstitial
AC-1-4E; San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 65-M12003-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Michelle Swift

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9PLM

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01478

Due Date:
08/15/2013
(Thursday)
AE

MS

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-4E City/State (Required): San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop Signature: [illegible] Date/Time: 8/9/13

Received by: KT HARRIS Signature: K Harris Date/Time: 8/12/13

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 13-08-01479

Client: AEHS
4402 Center Gate
San Antonio, TX 78217

Received Date: 08/12/2013
Analyzed Date: 08/14/2013
Reported Date: 08/14/2013

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-6A; San Antonio, TX

Client Number: 45-5371

Fax Number: 210-656-8499

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01479-001	1-DM		White Brittle; Homogeneous	NAD	100% Non-Fibrous
13-08-01479-002	2-DM		White Brittle; Homogeneous	NAD	100% Non-Fibrous
13-08-01479-003	3-DM		White Brittle; Homogeneous	NAD	100% Non-Fibrous
13-08-01479-004	4-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous
13-08-01479-005	5-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01479

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-6A;
San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
13-08-01479-006	6-CM		White Brittle; Brown Fibrous; Inhomogeneous	NAD	55% Cellulose 45% Non-Fibrous
13-08-01479-007	7-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous
13-08-01479-008	8-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous
13-08-01479-009	9-PM		White Adhesive; Homogeneous	NAD	100% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 45-5371 Report Number: 13-08-01479

Project/Test Address: Audie Murphy VA - 1st Interstitial AC1-6A;
San Antonio, TX

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials

QC Sample: 18-M11995-3

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Sami Hosn

Reviewed By Authorized Signatory: Tasha Eaddy

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

9PLM

EHS Laboratories™

Environmental Hazards Services, LLC

www.leadlab.com
(800)347-4010
(804)275-4907 (fax)

7469 Whitepine Rd
Richmond, VA
23237

First Positive Stop
Point Count Any Trace Amounts

Asbestos Chain-of-Custody

13-08-01479

Due Date:
08/15/2013
(Thursday)
AE

S

Company Name: AEHS Inc. Address: 4402 Centergate City/State/Zip: San Antonio,TX 78217

Phone: (210) 656-9300 Fax: (210) 656-8499 E-mail: mbishop@aehs-sa.com Acct. Number: 45-5371

Project Name / Testing Address: Audie Murphy VA-1st Interstitial AC-1-6A **City/State (Required):** San Antonio, TX

Collected by: Matthew Bishop Purchase Order Number:

Turn Around Times : *If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

____ 1 - Day ____ 2 - Day ✓ 3 - Day ____ Same Day (Must Call Ahead) ____ Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS							AIR					COMMENTS
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Chatfield (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)	Total Time (minutes)	Volume (Total Liters)	
1	1-DM	8/8/13	✓												Duct Mastic
2	2-DM	8/8/13	✓												"
3	3-DM	8/8/13	✓												"
4	4-CM	8/8/13	✓												Ceiling Material
5	5-CM	8/8/13	✓												"
6	6-CM	8/8/13	✓												"
7	7-PM	8/8/13	✓												Pipe Mastic
8	8-PM	8/8/13	✓												"
9	9-PM	8/8/13	✓												"
10															

Released by: M. Bishop Signature: [illegible] Date/Time: 8/9/13

Received by: KT HARRIS Signature: [illegible] Date/Time: 8/12/13