22 July 2026

Salient Characteristics
Motorola Dispatch Console Upgrade/Replacement

SOLUTION DESIGN HIGHLIGHTS SHALL INCLUDE:

- (8) AXS Dispatch Consoles shall include:
    a. Microsoft Windows, McAfee Antivirus, O/S Hardening
    b. (1) 22" Touch Screen Monitor, Keyboard, Mouse, External USB DVD
    c. (4) Speakers
    d. (2) Binaural Noise-Canceling Headsets
    e. (2) Headset Jacks
    f. (1) Footswitch
    g. (1) Gooseneck Microphone
    h. Internal Hardware Security Module
    i. (1) Tower UPS Per position
- Reuse of existing Trade Agreements Act (TAA) Networking Equipment at each of the existing Sites
    a. TAA Routers
    b. TAA Switches
- Installations shall be performed according to the Motorola Solutions manual "Standards and Guidelines for Communication Sites (R56)."
- Shall verify system configuration, optimize, and perform in-field functional acceptance testing for the system.
- Shall provide Cutover Plan activities as required.
- Shall uninstall and remove existing system antennas, cables, and equipment, as required and in accordance with the agreed-upon cutover plans.
- Shall provide "as-installed" documentation, customized for our system.
- Shall provide Training Classes for up to 12 people, Monday – Friday at 8:00 AM – 5:00 PM, Central Standard Time (CST)