EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Machine Gun Bunker damage



EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Machine Gun Bunker damage with Superficial SACON Walls Protecting from Assault Side.

EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Command Bunker damage



EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Command Bunker with Superficial SACON Walls Protecting from Assault Side.

EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Machine Gun Bunker opening damage (outside view)

EXHIBIT Z - JMMU Trench System Repairs

JMMU Trench System Machine Gun Bunker opening damage (inside view)



Install plywood between wood opening and superficial SACON to prevent hand-grenade from catching and bouncing back (header and jambs). Replace 2x4s at opening like original.