

IFB No.: HSR26-07 – Industrial Door / Residential Door / Rollup Door Maintenance and Repair Services

Questions and Answers

8/19/2026

No	Question	Response
1	One of the requirements for this IFB is a C60 license. The work required in this IFB does not meet the need for a C60 welding contractor license. The C61/D28 is all that should be required for this project. This is not a combination of licensing that is generally possessed by one company as the C61/D28 allows for welding as needed. Can the C60 license requirement be removed from this IFB?	Upon review of the scope of work of this agreement and the services that are permitted under a Contractors State License Board C61/D28 license, it has been determined that the C60 license is not required. The requirement for a C60 license is therefore removed from this Invitation for Bid (IFB).