APPENDIX A – SITE PHOTOS

Figure 2: Damaged Transformer

Figure 3: Damaged Transformer



Figure 4: Damaged Transformer

Figure 5: Damaged Transformer

Figure 6: Damaged Transformer

Figure 7: Damaged Transformer

Figure 8: Damaged Transformer