Embassy of The United States of America

Rome, Italy

U.S. CONSULATE GENERAL NAPLES

CHILLER REPLACEMENT

PHOTOGRAPHIC REPORT

Facility Management

05/07/2026

Figure 1 - Chiller room entrance

Figure 2 – Chiller unit

Figure 3 – Chiller unit

Figure 4 – Chiller unit

Figure 5 – Chiller unit

Figure 6 – Chiller unit

Figure 7 – Chiller unit

Figure 8 – Chiller unit

Figure 9 – Chiller unit

Figure 10 – Condensing units

Figure 11 – Condensing units

Figure 12 – Condensing units

Figure 13 – Condensing units