PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Drawings



Figure 1. **Area with asbestos tile known to be underneath existing carpet.**

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Drawings



Figure 2.

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Drawings



Figure 3.

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Photos

Photos 1-2 (First Floor Offices)

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Photos

Photo 3 (First Floor Offices/Carpet Layers/Asbestos Tiles)

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Photos

Photo 4 (Stairs and Landing)

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Photos

<u>Photos 5-6 (Second Floor Offices)</u>

PROJECT OFFICE FLOORING REMOVAL
AND REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
HOP BROOK LAKE
MIDDLEBURY, CT
Informational Photos

<u>Photos 7-8 (Second Floor Offices)</u>