REHABILITATE POLEBRIDGE WATER SYSTEM

SITE PHOTOS

2024 TO 2025

Location – Polebridge Ranger Station Area



Google Maps View

Infiltration Gallery Area



Foot path access to Infiltration Gallery Area



Valve Vault and Infiltration Gallery

Infiltration Gallery Area

Valve Vault (precast concrete structure with cast iron lid)

Inside of Valve Vault

Infiltration Gallery Area

Existing Infiltration Gallery and its lids (concentric CMP filled with concrete and cast iron lids)



Inside of the existing Infiltration Gallery

Infiltration Gallery Area



Existing Infiltration Gallery detail, per 1980 plans, sheet 43

Infiltration Gallery Area

Abandoned water supply structure (CMP pipe with steel lid)

Inside of the abandoned water supply structure

Infiltration Gallery Area

Infiltration gallery geotechnical test pit, July 2025

Excavated material

Water Tank Area



Existing Water Tank area clearing

Existing Water Tank area clearing

Existing Water Tank



Existing Water Tank, 30’-5” length x 7’-11” diameter plastic tank

Existing Water Tank Area



Water Tank lids

Water Tank lids

Inside North Fork Road

Inside North Fork Road, facing north (downhill)

Inside North Fork Road, facing north (downhill)

Inside North Fork Road

Inside North Fork Road, facing south (uphill)

Inside North Fork Road, facing north (downhill)

Inside North Fork Road

Water main tree clearing, from Housing Area

Water main tree clearing, from Inside North Fork Road

Housing Area



Housing Area, facing south



Housing Area, facing north

Housing Area

Housing Area, facing south

Housing Area, facing B#97

Housing Area – B#97 Ranger Residence



B#97 north façade

B#97 water service in crawl space

Housing Area – B#97 Ranger Residence

B#97 south façade

Housing Area – B#1451 Strissel Cabin

B#1451 west façade



B#1451 west façade

Housing Area – B#1451 Strissel Cabin

B#97 south façade

Housing Area – B#1454 Laundry and Shower

B#1454 north façade

B#1454 north façade

Housing Area – B#1576 Dorm and B#1865 School to Park Cabin



B#1576 north façade

B#1576 and B#1865

Housing Area – B#1576 Dorm

B#1594, existing water service entry

B#1594 existing water service entry

Housing Area – B#1865

B#1865, north façade



B#1865 inside of crawlspace access hatch

Maintenance Area

Facing north towards Maintenance Area

Facing northeast towards Maintenance Area

Maintenance Area



Maintenance Area, facing south



Maintenance Area, facing north

Maintenance Area - B#98 Cabin

B#98 and water service curb stops

Maintenance Area – B#353 Ranger Office

B#353 west façade

B#353 south façade

Maintenance Area - B#1448 Fire Cache, Ranger Storage, Chlorinator

B#1448 north façade



B#1448 west façade

Maintenance Area - B#1448 Fire Cache, Ranger Storage, Chlorinator



Chlorination Room

Chlorination Room

Maintenance Area - B#1448 Fire Cache, Ranger Storage, Chlorinator

Chlorination Room

Chlorination Room

Maintenance Area – B#1576 Radio Shed



B#1576, west façade

B#1576

Ranger Station Area

Park Entrance



Culvert in front of B#1455

Ranger Station Area

B#1455 and Solar Array

Solar Array and Staging Area

Ranger Station Loop – B#1455 Ranger Station

B#1455 south façade

B#1455 south façade

Staging Areas

Bowman Pit Staging Area

Covey Meadow Trailhead Staging Area