Figures (1-14) depicts as-built, existing windows inside the command suite, conference room, and exterior of the building.



(Figure 1, As-Built Windows Dimensions)

(Figure 2, Command Suite, Room 322, Existing Windows/Frames, Locks/Latches Standardized Throughout Command Suite)

(Figure 3, Command Suite, Room 322, Frame/Trim/Screen Standard Throughout)



(Figure 4, Command Suite, Room 325)

(Figure 5, Command Suite, Room 328, Existing Windows/Frames)

(Figure 6, Command Suite, Room 328, Existing Windows/Frames)

(Figure 7, Command Suite, Room 329, Existing Windows/Frames)

(Figure 8, Command Suite, Wing Executive, Existing Windows/Frames)

(Figure 9, Conference Room, Existing Windows/Frames)

(Figure 10, Conference Room, Existing Windows/Frames)

(Figure 11, Conference Room, Existing Windows/Frames)

(Figure 12, Conference Room, Existing Windows/Frames)

(Figure 13, Conference Room, Existing Windows/Frames)

(Figure 14, Exterior of Building, Glazed Windows)